

National Transportation Safety Board  
Washington, DC 20594

Printed on : 9/14/2010 11:46:16 PM

Brief of Accident

Adopted 07/16/2010

DCA08MA098 File No. 0	09/19/2008	Columbia, SC	Aircraft Reg No. N999LJ	Time (Local): 23:53 EDT		
Make/Model: Learjet / LR60				Fatal	Serious	Minor/None
Engine Make/Model:			Crew	2	0	0
Aircraft Damage: Destroyed			Pass	2	2	0
Number of Engines: 2						
Operating Certificate(s): On-demand Air Taxi						
Name of Carrier: Global Exec Aviation						
Type of Flight Operation: Non-scheduled; Domestic; Passenger Only						
Reg. Flight Conducted Under: Part 135: Air Taxi & Commuter						
Last Depart. Point: Same as Accident/Incident Location				Condition of Light: Night		
Destination: Van Nuys, CA				Weather Info Src: Weather Observation Facility		
Airport Proximity: Off Airport/Airstrip				Basic Weather: Visual Conditions		
				Lowest Ceiling: None		
				Visibility: 10.00 SM		
				Wind Dir/Speed: 060 / 007 Kts		
				Temperature (°C): -7		
				Precip/Obscuration:		
Pilot-in-Command	Age:	Flight Time (Hours)				
Certificate(s)/Rating(s)		Total All Aircraft: Unk/Nr				
Airline Transport		Last 90 Days: Unk/Nr				
		Total Make/Model: Unk/Nr				
Instrument Ratings		Total Instrument Time: Unk/Nr				

The NTSB's full report is available at <http://www.ntsbt.gov/publictn/publictn.htm>. The Aircraft Accident Report number is NTSB/AAR-10/02. On September 19, 2008, about 2353 eastern daylight time, a Bombardier Learjet Model 60, N999LJ, owned by Inter Travel and Services, Inc., and operated by Global Exec Aviation, overran runway 11 during a rejected takeoff at Columbia Metropolitan Airport, Columbia, South Carolina. The captain, the first officer, and two passengers were killed; two other passengers were seriously injured. The nonscheduled domestic passenger flight to Van Nuys, California, was operated under 14 Code of Federal Regulations Part 135. Visual meteorological conditions prevailed, and an instrument flight rules flight plan was filed.

Updated at Jul 16 2010 4:51PM

Brief of Accident (Continued)

DCA08MA098				
File No. 0	09/19/2008	Columbia, SC	Aircraft Reg No. N999LJ	Time (Local): 23:53 EDT

---

OCCURRENCES

Prior to flight - Aircraft maintenance event  
Takeoff - Sys/Comp malf/fail (non-power)  
Takeoff-rejected takeoff - Runway excursion  
Post-impact - Fire/smoke (post-impact)

FINDINGS

Aircraft-Aircraft systems-Landing gear system-Tire casing-Incorrect service/maintenance - C  
Aircraft-Aircraft systems-Landing gear system-Tire casing-Failure  
Organizational issues-Support/oversight/monitoring-Oversight-Oversight of maintenance-Operator - C  
Personnel issues-Action/decision-Action-Incorrect action selection-Pilot - C  
Personnel issues-Task performance-Use of equip/info-Use of policy/procedure-Pilot - C  
Organizational issues-Development-Design-Equipment design-Manufacturer - F  
Organizational issues-Development-Selection/certification/testin-Equip certification/testing-FAA/Regulator - F  
Organizational issues-Development-Selection/certification/testin-Equip certification/testing-Operator - F  
Organizational issues-Development-Selection/certification/testin-Personnel selection/training-Not specified - F  
Personnel issues-Task performance-Communication (personnel)-CRM/MRM techniques-Flight crew - F  
Organizational issues-Support/oversight/monitoring-Oversight-Equipment monitoring-Manufacturer - F  
Organizational issues-Support/oversight/monitoring-Oversight-Equipment monitoring-FAA/Regulator - F  
Aircraft-Aircraft power plant-Engine exhaust-Thrust reverser-Design - F  
Aircraft-Aircraft oper/perf/capability-Performance/control parameters-Powerplant parameters-Attain/maintain not possible

Findings Legend: (C) = Cause, (F) = Factor

---

The National Transportation Safety Board determines the probable cause(s) of this accident as follows.

The operator's inadequate maintenance of the airplane's tires, which resulted in multiple tire failures during takeoff roll due to severe underinflation, and the captain's execution of a rejected takeoff (RTO) after V1, which was inconsistent with her training and standard operating procedures.

Contributing to the accident were (1) deficiencies in Learjet's design of and the Federal Aviation Administration's (FAA) certification of the Learjet Model 60's thrust reverser system, which permitted the failure of critical systems in the wheel well area to result in uncommanded forward thrust that increased the severity of the accident; (2) the inadequacy of Learjet's safety analysis and the FAA's review of it, which failed to detect and correct the thrust reverser and wheel well design deficiencies after a 2001 uncommanded forward thrust accident; (3) inadequate industry training standards for flight crews in tire failure scenarios; and (4) the flight crew's poor crew resource management (CRM).